

To: GAP Professional Products Users

Bulletin Number: GAP-0224-1

Subject: GAP Lifetime Protection Plan Exclusions

In order to facilitate our GLPP program, we have created a list of vehicles/manufacturers/components that are not covered under the GAP Lifetime Protection Plan as they are considered a Pre-existing Condition and/or Manufacturer defect.

OEM	Years	System	Notes
Hyundai	2010 -	Engine	2011-2014MY Sonata (YFa)
	Present		2015-2019MY Sonata (LFa)
			2013-2018MY Santa Fe Sport (AN)
			2019MY Santa Fe (TMa)
			2014-2015MY Tucson (LM) equipped with Theta 2.4 GDI Engine
			2019MY Tucson (TL) equipped with Theta 2.4 GDI Engine
			2019MY Veloster N (JSN)
			2019-2020MY Elantra (AD) with Nu 2.0 MPI Atkinson Engine
			2019-2021MY Kona (OS) with Nu 2.0 MPI Atkinson Engine
			2019-2021MY Veloster (JS) with Nu 2.0 MPI Atkinson Engine
			2011-2015 Elantra (UD) with Nu 1.8 MPI
			2015-2016 Elantra (MD) with Nu 1.8 MPI
			2013 Elantra Coupe (JK) with Nu 1.8 MPI
			2013 Elantra GT (GD) with Nu 1.8 MPI
			2010-2012 Sata Fe (CMa) with Theta 2.4 MDI Engine
			2010-2013 Tucson (LM) with Theta 2.4 MDI Engine
			2014-2015 Tucson (LM) with Nu 2.0 MPI Engine
			2016-2021 Tucson (TL) with Nu 2.0 GDI Engine
			2014-2016 Elantra (MD) with Nu 2.0 GDI Engine
			2014-2015 Elantra Coupe (JK) with Nu 2.0 GDI Engine
			2014-2017 Elantra GT (GD) with Nu 2.0 GDI Engine
			2018-2020 Elantra PT (PD) with Nu 2.0 GDI Engine
			2011-2015 Sonata Hybrid (YF HEV) with Theta-II 2.4 MPI Engine
			2016-2019 Sonata Hybrid (LF HEV & LF PHEV) Nu 2.0 GDI Engine
			2012-2017 Veloster (FS) Gamma 1.6 GDI Engine
KIA	2014 -	Engine	
	Present		
General Motors	2016 -	V8 Engine	Failure known to be caused by faulty lifters.
	Present	5.3L/6.2L	, , , , , , , , , , , , , , , , , , , ,
		0.02/0.22	

^{*}This list is subject to change without notice and is accurate as of February 24, 2025.

The complete terms, conditions & exclusions can be found on our website at www.gappro.ca/glpp